

System Element (Ln #/Gen ID)	For Work On:	Start Time	End Time	Short Description / Purpose of Request	System Restrictions	Outage Type
L-6548	3C B72	2020-03-08	2020-03-08	Isolate 3C Bus 72 for Trip Testing		Outage (equip. only)
L-7009	99W-T71	2020-04-01	2020-04-05	C Inspection 99W-T71	40MW South Shore generation minimum. CT on SYNC. L6002 must be closed through from 90H to 99W	Outage (equip. only)
L-6552	4C-620	2020-04-01	2020-04-29	Breaker Replacement	Reducing SPS Arming Levels Limiting Onslow Import. Generation restrictions apply	Outage (equip. only)
L-6531	50W-P6531	2020-04-01	2020-04-02	C Inspection 50W-P6531		Outage (equip. + Line)
L-6054	43V-604	2020-04-01	2020-04-03	C Inspection 43V-604	Generation Restrictions Apply. Requires low load conditions	Outage (equip. only)
L-6054	43V-CT604	2020-04-01	2020-04-02	C Inspection 43V-CT604	Generation Restrictions Apply. Requires low load conditions	Outage (equip. only)
L-6006	99W-606	2020-04-01	2020-04-03	C Inspection 99W-606		Outage (equip. only)
L-6006	99W-P6006	2020-04-01	2020-04-02	C Inspection 99W-P6006		Outage (equip. + Line)
L-6006	99W-CT606	2020-04-01	2020-04-02	C Inspection 99W-CT606		Outage (equip. only)
L-6006	50W-P6006	2020-04-01	2020-04-02	C Inspection 50W-P6006		Outage (equip. + Line)
67N-T82	67N-T82	2020-04-09	2020-04-18	C Inspection 67N-T82	ONI 750, Nothing on the TIE.	Outage (equip. only)
L-6516	2S-604	2020-04-13	2020-05-08	Breaker Replacement	CBX - 830MW, Onslow Import Normal, Generation restrictions apply	Outage (equip. + Line)
L-6051	17V-PB2	2020-04-15	2020-04-16	C Inspection 17V-PB2		Outage (equip. only)
L-6001	1N-P6001	2020-04-15	2020-04-16	C Inspection 1N-P6001		Outage (equip. + Line)
L-7011	101S-751	2020-05-01	2020-05-01	Vendor Repairs	East End X at East Bay - 875/1000 MW, Onslow Import 1050/1150 MW, Generation restrictions apply, Lower SPS arming limits	Outage (equip. + Line)
L-6040	91H-606	2020-05-01	2020-05-03	C Inspection 91H-606		Outage (equip. only)
L-5500	50N-521	2020-05-01	2020-05-03	C Inspection 50N-521		Outage (equip. only)
L-5500	50N-PB57	2020-05-01	2020-05-02	C Inspection 50N-PB57		Outage (equip. only)
L-5026	12V-PB51	2020-05-01	2020-05-02	C Inspection 12V-PB51	Generation restrictions apply to local generation	Outage (equip. only)
L-7021	101S-752	2020-05-02	2020-05-02	Vendor Repairs	Generation restrictions apply. East End Export at Sydney: 350/500 MW	Outage (equip. + Line)
L-6515	4C-621	2020-05-04	2020-05-29	Breaker Replacement	Onslow Import 800 to 1000 depending on local generation, Generation Restrictions apply, SPS arming levels reduced	Outage (equip. only)
1C-B62	1C-689	2020-05-04	2020-05-29	Breaker Replacement		Outage (equip. only)
1C-B61	1C-689	2020-05-04	2020-05-06	C Inspection 1C-689		Outage (equip. only)
3S-B61	3S-B61 Protection	2020-05-06	2020-05-17	Replace Bus Protection relays on 3S 138kv bus - B61		Outage (equip. + Line)
L-6533	2S-607	2020-05-11	2020-05-13	C Inspection 2S-607	Operate CT units in synchronous condenser mode. Generation restrictions apply in summer	Outage (equip. only)
L-6533	2S-607	2020-05-11	2020-06-05	Breaker Replacement	Operate CT units in synchronous condenser mode. Generation restrictions apply in summer	Outage (equip. + Line)
L-6014	91H-607	2020-05-15	2020-05-17	C Inspection 91H-607	Generation restrictions apply	Outage (equip. only)
L-6008	90H-612	2020-05-15	2020-05-17	C Inspection 90H-612		Outage (equip. only)
L-8004	101S-P8004	2020-06-01	2020-06-02	C Inspection 101S-P8004	Hastings From 600MW /725, L7011+L7012 500 /600, Mainland at Hastings 570 /680, Generation restrictions apply	Outage (equip. + Line)
L-8004	101S-L8004	2020-06-01	2020-06-02	NPCC Trip Testing 101S-L8004	Hastings From 600MW /725, L7011+L7012 500 /600, Mainland at Hastings 570 /680, Generation restrictions apply	Outage (equip. + Line)
L-8004	L-8004	2020-06-01	2020-06-03	Canso Crossing tying in the new line	Hastings From 600MW /725, L7011+L7012 500 /600, Mainland at Hastings 570 /680, Generation restrictions apply	Outage (Line only)
L-7019	L7019 Outage	2020-06-01	2020-06-26	L7019 outage for structure and insulator replacements.	Cape Breton Export 850/1000, Onslow Import 1050/1150	Outage (Line only)
L-7018	67N-P7018	2020-06-01	2020-06-02	C Inspection 67N-P7018	Onslow 740/900, MDRR correction 50 Mvar	Outage (equip. + Line)

L-7002	67N-P7002	2020-06-01	2020-06-02 C Inspection 67N-P7002	Onslow South 670/ 850	Outage (equip. + Line)
L-7002	L7002 Outage	2020-06-01	L7002 outage for structure and insulator replacements.	Onslow South 670/ 850	Outage (Line only)
L-6523	47C-673	2020-06-01	2020-06-03 C Inspection 47C-673		Outage (equip. only)
L-6523	47C-673	2020-06-01	2020-06-26 Breaker Replacement		Outage (equip. only)
L-6515	4C-622	2020-06-01	2020-06-26 Breaker Replacement	Onslow Import 800 to 1000 depending on local generation, Generation Restrictions apply, SPS arming levels reduced	Outage (equip. only)
L-6021	9W-T2	2020-06-01	2020-06-05 C Inspection 9W-T2	CT must be available for Sync	Outage (equip. only)
L-6021	9W-PB52	2020-06-01	2020-06-02 C Inspection 9W-PB52	CT must be available for Sync	Outage (equip. only)
L-6010	90H-609	2020-06-01	2020-06-03 C Inspection 90H-609		Outage (equip. only)
L-6008	90H-611	2020-06-01	2020-06-03 C Inspection 90H-611		Outage (equip. only)
L-5027	30W-507	2020-06-01	2020-06-26 Breaker Replacement		Outage (equip. + Line)
301NS Pole 1	ML P1	2020-06-01	2020-06-04 ML P1 Annual shutdown maintenance outage		System Maintenance
301NS Pole 2	ML P2	2020-06-04	2020-06-07 Outage		System Maintenance
L-6539	2S-603	2020-06-08	2020-07-03 Breaker Replacement	Generation restriction apply, Reduce SPS arming levels	Outage (equip. + Line)
L-6503	1N-623	2020-06-30	2020-07-02 C Inspection 1N-623	Onslow Import: 820 MW, Generation Restrictions apply, Lower SPS arming levels. Generation Restrictions	Outage (equip. only)
L-6552	4C-623	2020-07-01	2020-07-29 Breaker Replacement	Reducing SPS Arming Levels Limiting Onslow Import. Generation restrictions apply	Outage (equip. only)
L-6518	2C-647	2020-07-01	2020-07-03 C Inspection 2C-647		Outage (equip. only)
L-6518	47C-674	2020-07-01	2020-07-30 Breaker Replacement		Outage (equip. only)
L-6021	9W-516	2020-07-01	2020-07-29 Breaker Replacement	CT must be available for Sync	Outage (equip. + Line)
L-6002	90H-601	2020-07-01	2020-07-29 Breaker Replacement		Outage (equip. only)
1N-B61	1N-PB61	2020-07-01	2020-07-02 C Inspection 1N-PB61		Outage (equip. only)
1N-B61	1N-619A	2020-07-01	2019-07-04 1N-619A Replacement		Outage (equip. only)
L-6549	L6549 Outage	2020-08-01	L6549 outage for structure and insulator replacements.		Outage (Line only)
L-6514	74N-P6514	2020-08-01	2020-08-02 C Inspection 74N-P6514		Outage (equip. + Line)
L-6024	9W-563	2020-08-01	2020-08-01 Breaker Replacement	CT must be available for Sync	Outage (equip. + Line)
L-6518	47C-675	2020-08-03	2020-08-05 C Inspection 47C-675		Outage (equip. only)
L-6518	47C-675	2020-08-03	2020-08-28 Breaker Replacement		Outage (equip. only)
L-6507	9W-563	2020-08-15	2020-08-15 Breaker Replacement		Outage (equip. + Line)
L-6507	79N-606	2020-08-15	2020-08-15 Breaker Replacement		Outage (equip. + Line)
L-6551	30N-P6551	2020-08-18	2020-08-19 C Inspection 30N-P6551		Outage (equip. + Line)
L-6613	1N-613	2020-09-01	2020-09-03 C Inspection 1N-613	NB Tie Imports and Exports 300MW, SPS available	Outage (equip. only)
L-6613	1N-P6613	2020-09-01	2020-09-02 C Inspection 1N-P6613	NB Tie Imports and Exports 300MW, SPS available	Outage (equip. + Line)
L-6003	90H-606	2020-09-01	2020-09-03 C Inspection 90H-606	Generation restrictions apply	Outage (equip. only)
L-6003	90H-606	2020-09-01	2020-09-25 Breaker Replacement	Generation restrictions apply	Outage (equip. only)
L-5527	57C-527	2020-09-01	2020-09-30 Breaker Replacement		Outage (equip. + Line)
3C-B72	3C-PB72	2020-10-01	2020-10-01 3C-PB72 C Maintenance		Outage (equip. only)
L-6047	101W-CT647	2020-10-01	2020-10-02 C Inspection 101W-CT647		Outage (equip. only)
L-6002	90H-601	2020-10-01	2020-10-03 C Inspection 90H-601		Outage (equip. only)
L-6002	90H-P6002	2020-10-01	2020-10-02 C Inspection 90H-P6002		Outage (equip. + Line)
L-5544	Re-Development	2020-10-01	2020-10-31 Re-Development Project	Generation Restrictions Apply	Outage (equip. + Line)

L-8001	L8001 Outage	1900-01-25	L8001 outage for insulator replacements.		Outage (Line only)
L-7005	L7005 Outage	1900-01-18	L7005 Outage for structure and insulator replacements.	Cape Breton Export 850/1000, Onslow Import 1050/1150, SPS arming levels reduced. Mainland at Hastings 340/420	Outage (Line only)