

System Element (Ln #/Gen ID)	For Work On:	Start Time	From Station	End Time	Short Description / Purpose of Request	System Restrictions
L-7021	OHGW L-7021	2020-04-01 7:00	101S-Woodbine	2020-04-01 14:00	REPAIRS TO OHGW ON L-7021 4C-620 Breaker replacement.	Generation restrictions apply. East End Export at Sydney: 350/500 MW
L-6552	4C-620	2020-04-01 10:00	4C-Antigonish (Loch.	2020-04-29 12:00		Reducing SPS Arming Levels Limiting Onslow Import, Generation restrictions apply.
L-7019	L7019 Outage	2020-04-06 0:00	67N-Onslow	2020-05-07 0:00	L7019 outage for structure and insulator replacements.	Cape Breton Export 850/1000, Onslow Import 1050/1150, SPS limits reduced
L-5026	12V-503	2020-04-06 0:00	13V-Gulch Hydro	2020-04-10 0:00	Switch Repair	Generation restrictions apply to local generation
L-6001	L6001(132H - 127H) Outage	2020-04-06 6:00	1N-Onslow	2020-04-07 18:00	Outage on L6001 (132H - 127H)	
67N-T82	67N-T82	2020-04-06 9:00	67N-Onslow	2020-04-17 15:00	C Inspection 67N-T82, 67N-PB32, 67N-PT82, replace bushings.	ONI 750 (Group 5 SPS Cannot be Armed) Nothing on the TIE. (8002,8003,6513 must be in service)
L-6040	L6040 (139H-132H) and L6042	2020-04-07 7:00	91H-Tufts Cove	2020-04-08 17:00	L6040 (139H-132H) and L6042 simultaneous outage for OHGW	
L-6539	2S-603	2020-04-13 0:00	2S-Victoria Junction	2020-05-02 0:00	Breaker Replacement	Generation restriction apply, Reduce SPS arming levels
L-7004	L-7004	2020-04-14 9:00	91N-Dalhousie Mtn.	2020-04-14 14:00	Trip testing and protection channel testing on L-7004.	Cape Breton Export 850 /1000, Onslow Import 1050/1150, lower SPS arming levels
L-5500	50N-521	2020-04-16 9:00	50N-Trenton	2020-04-17 14:00	C Inspection 50N-521	
2C-B63	2C-602	2020-04-21 9:00	2C	2020-04-21 13:00	Isolate 2C-602 to Investigate/Repair SF6 leaks	
L-6001	82V substation equipment	2020-04-22 10:00	1N-Onslow	2020-05-07 0:00	C-Maintenance on 82V equipment	
L-5026	74V-504	2020-04-27 0:00	13V-Gulch Hydro	2020-05-04 0:00	Switch Repairs	Generation restrictions apply to local generation
L-6001	127H-603	2020-05-01 0:00	1N-Onslow	2020-05-10 0:00	Switch Replacement	
1C-B62	1C-689	2020-05-02 0:00	1C	2020-05-21 0:00	Breaker Replacement	
L-6533	2S-607	2020-05-02 0:00	2S-Victoria Junction	2020-05-21 0:00	Breaker Replacement	Generation restrictions apply
L-8001	L8001 Outage	2020-05-04 0:00	67N-Onslow	2020-06-04 0:00	L8001 outage for insulator replacements.	
L-6515	4C-621	2020-05-04 10:00	2C-Port Hastings	2020-05-29 12:00	Breaker Replacement. Replace Bus Protection relays on 3S 138kv bus - B61	Onslow Import 800 to 1000 depending on local generation, Generation Restrictions apply, SPS arming levels reduced
3S-B61	3S-B61 Protection	2020-05-06 0:00	3S	2020-05-17 0:00	This will open the 138kv loop impacting L-6538/L-6539.	
L-7005	L7005 Outage	2020-05-11 0:00	67N-Onslow	2020-06-15 0:00	L7005 Outage for structure and insulator replacements.	Cape Breton Export 850/1000, Onslow Import 1050/1150, SPS arming levels reduced. Mainland at Hastings 340/420
L-6001	127H-604	2020-05-11 0:00	1N-Onslow	2020-05-21 0:00	Switch Replacement	
L-6033	2H-603	2020-05-11 0:00	103H-Lakeside	2020-05-11 0:00	Switch Replacement	Generation Restrictions Apply
L-6033	2H-604	2020-05-12 0:00	103H-Lakeside	2020-05-12 0:00	Switch Repair	Generation Restrictions Apply
L-6523	47C-673	2020-05-30 0:00	1C-Point Tupper	2020-06-18 0:00	Breaker Replacement	
101S-T81	101S-881	2020-06-01 0:00	101S-Woodbine	2020-06-05 0:00	Breaker Replacement	
L-6515	4C-622	2020-06-01 10:00	2C-Port Hastings	2020-06-26 12:00	4C-622 Breaker replacement.	Onslow Import 800 to 1000 depending on local generation, Generation Restrictions apply, SPS arming levels reduced
L-6518	47C-674	2020-07-01 0:00	2C-Port Hastings	2020-07-30 0:00	Breaker Replacement	
L-6002	99W-622B	2020-07-01 0:00	90H-Sackville	2020-07-05 0:00	Switch Repairs	
L-6552	4C-623	2020-07-02 10:00	4C-Antigonish (Loch.	2020-07-30 12:00	4C-623 Breaker Replacement.	Reducing SPS Arming Levels Limiting Onslow Import, Generation Restrictions
L-6002	90H-601	2020-07-04 0:00	90H-Sackville	2020-07-23 0:00	Breaker Replacement	
L-6021	9W-516	2020-07-04 0:00	30W-Souriquois	2020-07-23 0:00	Breaker Replacement	CT must be available for Sync
L-6523	47C-674A	2020-07-04 0:00	1C-Point Tupper	2020-07-13 0:00	Switch Repair/Replacement	
L-6518	47C-674B	2020-07-04 0:00	2C-Port Hastings	2020-07-13 0:00	Switch Repair/Replacement	
1C-B62	1C-684A	2020-07-12 0:00	1C	2020-07-26 0:00	Switch Repair/Replacement	
1C-B61	1C-688	2020-07-20 0:00	1C	2020-08-01 0:00	Switching Replacement	
L-6024	9W-563	2020-08-01 0:00	50W-Milton	2020-08-01 0:00	Breaker Replacement	CT must be available for Sync
L-6507	9W-563	2020-08-01 0:00	50N-Trenton	2020-08-20 0:00	Breaker Replacement	
L-6507	79N-606	2020-08-01 0:00	50N-Trenton	2020-08-20 0:00	Breaker Replacement	
L-6518	47C-675	2020-08-03 0:00	2C-Port Hastings	2020-08-28 0:00	Breaker Replacement	
1C-B62	1C-684B	2020-08-10 0:00	1C	2020-08-24 0:00	Switch Replacement	
1C-B62	1C-648A	2020-08-10 0:00	1C	2020-08-10 0:00	Switch Replacement	
L-6003	90H-606	2020-09-05 0:00	90H-Sackville	2020-09-24 0:00	Breaker Replacement	Corridor Restriction
L-5527	57C-527	2020-09-05 0:00	57C-Salmon River Lak	2020-09-24 0:00	Breaker Replacement	
L-6549	L6549 Outage	2020-09-07 0:00	5S-Glen Tosh	2020-09-25 0:00	L6549 outage for structure and insulator replacements.	
L-7002	L7002 Outage	2020-09-14 0:00	67N-Onslow	2020-10-09 0:00	L7002 outage for structure and insulator replacements.	Onslow South 670/ 850
301NS Pole 1	ML P1	2020-09-28 7:00	301NS-Woodbine DC	2020-10-01 8:00	ML P1 Annual shutdown maintenance outage	
301NS Pole 2	ML P2	2020-10-01 0:00	301NS-Woodbine_DC	2020-10-04 10:00	ML P2 Annual Shutdown Maintenance Outage	
L-5544	Hydro Re-Development	2020-10-01 0:00	3W - Big Falls	2020-10-31 0:00	Hydro Re-Development Project	Generation Restrictions Apply
L-6516	59C-603	2020-10-05 0:00	2C-Port Hastings	2020-10-09 0:00	Breaker Replacement	CBX - 830MW, Onslow Import Normal, Generation restrictions apply
L-8004	L-8004	2020-10-07 0:00	79N-Hopewell	2020-10-09 0:00	tying in the new line	Hastings From 600MW /725, L7011+L7012 500 /600, Mainland at Hastings 570 /680, Generation restrictions apply
L-6516	2S-604	2020-10-24 0:00	2C-Port Hastings	2020-10-24 0:00	Breaker Replacement	CBX - 830MW, Onslow Import Normal, Generation restrictions apply

*Dates and outages may be significantly impact by the currently evolving COVID 19 situation.